



Solusi masalah COM Port tidak terdeteksi Seperti dibawah ini :




1. **Download** USB Driver dari website BRT atau klik [disini](#)




MAPPING R15	DOWNLOAD
JUKEN 5 V1.3.21 (INDONESIA VERSION)	DOWNLOAD
JUKEN 5 ANDROID V1.1.12	DOWNLOAD
SMART CHARGER V1.1.2	DOWNLOAD
SMART CHARGER ANDROID V1.1.3	DOWNLOAD
BRT USB DRIVER	DOWNLOAD
NET FRAMEWORK 4.6	DOWNLOAD
ANDROID SMART CHARGER FB V1.1.5	DOWNLOAD

2. Setelah download selesai, akan ada file bernama “BrtUsbDriverFix.zip”



Name	Date modified	Type	Size
Today (1)			
BrtUsbDriverFix.zip	1/14/2020 4:50 PM	Compressed (zipp...	3,075 KB

3. **Extract** isi dari file tersebut ke folder terpisah




Name	Date modified	Type
dpinst	8/2/2019 1:53 PM	File folder
Driver	8/2/2019 1:53 PM	File folder
FixUsbDriver.bat	8/2/2019 1:53 PM	Windows Batch File
PL2303_Prolific_DriverInstaller_v1.5.0.exe	1/24/2014 9:44 AM	Application

4. Setelah di extract, didalam folder extract berisi 4 file, yaitu :

- a) Dpinst
- b) Driver
- c) FixUsbDriver.bat
- d) PL2303_Prolific_DriverInstaller_v1.5.0.exe


5. **Open** file “FixUsbDriver.bat”



Name	Date modified	Type
dpinst	8/2/2019 1:53 PM	File folder
Driver	8/2/2019 1:53 PM	File folder
FixUsbDriver.bat	8/2/2019 1:53 PM	Windows Batch File
PL2303_Prolific_DriverInstaller_v1.5.0.exe	1/24/2014 9:44 AM	Application

6. Bila keluar kotak promnt, Pilih Yes sampai kotak promnt tidak muncul lagi.

7. Cek Device Manager.



8. Bila tampilan Port sudah seperti gambar di atas, USB sudah bisa digunakan.